

 <b>HÄSSLEHOLM MILJÖ AB</b> <small>VI BRINNER FÖR EN HÅLLBAR FRAMTID</small>	<b>Document name</b>		
	Appendix A: Specific requirements for Hässleholm recycling centre (HKC)		
<b>Issued by</b> The safety committee	<b>Approved by/manager</b> Sven Carlsson	<b>Date</b> 1 july 2021	<b>Edition</b> 02

## **Appendix A Specific requirements for Hässleholm Recycling Centre (HKC)**


- The maximum speed throughout the area is 30 km/h, unless otherwise stated. Beware of crossing vehicles!
- Be aware of and adhere to signs, guardrails, and barriers.
- The following risk areas are present at the facility: Gas facility, zones with flammable and explosive substances, purification plants (using chemicals), and the like (see map). These areas pose a high risk of fire and explosion. Special precautions must be taken to prevent sparking and open flames.
- Vehicles that have been driven in landfill areas and on the surface of contaminated material must drive through a tyre wash before leaving (see map).
- Tipping outside of the designated tipping area is strictly prohibited. If you are uncertain, contact the weighing staff.
- Tipping must not take place on the surface of contaminated material without contacting staff on the surface.
- Workwear must always consist of at least safety shoes and warning clothing on the lower and upper body. Some work steps may require additional protective clothing and equipment. For questions about what requirements are set, contact the facility manager.
- First aid equipment is available at the following signposted locations: the weighing office (a defibrillator is also located here), the recycling centre (ÅVC, a defibrillator is also located here), and on board the company's vehicles. All staff are trained in CPR (training takes place every two years).
- Permits are required for hot work, which includes, for example, soldering, welding, and the use of hot air guns. Hot work must not be carried out within a radius of at least 10 metres from classified areas.
- In the event of an accident or other incident, the following contacts are used: During the daytime, the contact number is: +46 (0)451-26 66 00 - weighing office. At other times, call the emergency number: +46 (0)451-191 10. You can also contact the nearest employee at HMAB.
- The removal of equipment or material from the area is strictly prohibited. This is considered as theft and will be reported to the police.
- Photography and filming in the area is permitted only after seeking the permission of the recipient responsible for the visitor.
- Visitors/contractors at the facility must wear at least a high-visibility vest or high-visibility clothing when working or spending time outdoors. Other clothing may be required in other areas. HMAB's staff will inform you of this before work starts.
- Visitors/contractors must follow the instructions they are given regarding the use of personal protective equipment.
- HMAB is not responsible for any accompanying children or animals. To avoid injury, they must remain in the vehicle while you are in the area.

*> Part of the Municipality of Hässleholm*

 <b>HÄSLEHOLM MILJÖ AB</b> VI BRINER FÖR EN HÅLLBAR FRAMTID	<b>Document name</b> Appendix A: Specific requirements for Hässleholm recycling centre (HKC)		
	<b>Issued by</b> The safety committee	<b>Approved by/manager</b> Sven Carlsson	<b>Date</b> 1 july 2021



> Part of the Municipality of Hässleholm

 <b>HÄSSLEHOLM MILJÖ AB</b> <small>VI BRINER FÖR EN HÅLLBAR FRAMTID</small>	<b>Document name</b> Appendix A: Specific requirements for Hässleholm recycling centre (HKC)		
<b>Issued by</b> The safety committee	<b>Approved by/manager</b> Sven Carlsson	<b>Date</b> 1 july 2021	<b>Edition</b> 02

I have read and understood the above:

**Name (written) and company:**

---

**Date and signature:**

---

The signed part of the document is retained by HMAB.

*> Part of the Municipality of Hässleholm*